




---

CURA E MANUTENZIONE  
CARE AND MAINTENANCE TIPS  
SOIN ET ENTRETIEN  
REINIGUNGS-UND WARTUNGSTIPPS  
CUIDADO Y MANTENIMIENTO



# BRASS

---

Brass is a copper and zinc alloy, a material used mainly where a good mechanical resistance is required, but also for a merely decorative and aesthetic use.

**Brass sheets**, specifically **0.5mm thick**, are produced through continuous casting and following lamination. Shares of zinc are variable depending on needs and end-use. The material used in our products is, in detail, a special **alloy defined OT.63**: its workability is better than other alloys, it can keep the material's key features unaltered.

The **unique product's surface finish** and its particular dystonic and non uniform nature, is **manually moulded** by non mechanic or automated sanding, that is synonymous with care, professionalism and **focus on every single detail** of the end product. Each one different from the other, **each one original**, but perfectly comparable with all the others.



#### Maintenance:

Brass is a metal alloy. It features an excellent mechanical and chemical resistance, yet, at the same time, it is delicate due to its particular surface.

In order to avoid stains and spots, the operations described hereafter must be carried out on the whole surface, by making circular movements.

For ordinary maintenance, use a soft cloth moistened with water.

For deep cleaning, please use a soft cloth moistened with a small amount of non-abrasive neutral detergent without ammonia and/or vinegar (for instance a degreaser). At the end of the operation, rinse the surface with a soft cloth dampened with water and dry with a dry soft cloth.

#### It is recommended:

- To use mild soap and water and to dry with a clean soft cloth;
- To use any common neutral detergent, provided it does not contain neither chlorine nor chlorine derivatives, such as bleach and muriatic acid, ammonia and vinegar;
- Do not use any abrasive materials that would unavoidably scratch the surface;
- Avoid shocks and etchings by using blunt items capable of scratching the surface, subsequently removing its protective section;
- Avoid any deposit and prolonged retention of liquids to prevent long-lasting stains and marks from forming. Any liquids must be removed as soon as possible;
- Do not use any alcohol, stain removers, diluent, acetone, trichloroethylene, vinegar, ammonia, bleach, limescale remover, as well as liquids containing such substances;
- Do not use any abrasive powder detergents, capable of damaging the aesthetic and surface finish look;
- Do not drag any object on the top and do not insist to clean a single area of the top (it may alter its opacity);
- Try not to lay hot pots and objects, as well as ovens or small ovens that may cause deformations and yellowings.

MDF ITALIA spa  
Società Unipersonale

HEADQUARTER  
via fratelli cervi 4/A  
22066 mariano comense (CO)  
0039 031 7570301

SHOWROOM MILANO  
via della chiesa  
0039 02 58 317168

[info@mdfitalia.it](mailto:info@mdfitalia.it)  
[www.mdfitalia.it](http://www.mdfitalia.it)